

TRIAX A/S

TDX/TDH800 Release

5.1.1.42586

SUMMARY

Release description of TDX and TDH800 software release

Table of Content

Table of Content	2
1 Introduction	3
2 Requirements	3
3 New features	3
3.1 General	3
3.2 Frontend	3
3.3 Backend	3
4 Bug fixes	3
4.1 General:	3
4.2 Backend	3

1 Introduction

Purpose of this document is in short to describe features delivered in the software version it refers to.

2 Requirements

This release supports all TDX and TDH800 hardware, except prerelease modules shipped without serial number (before 2010-12-08).

3 New features

List of new features added in release 5.1.1.42586, since last release 5.0.1.41682.

3.1 General

- **Browser icon change to fit the newest design.**

3.2 Frontend

- **Service type list is updated so "HEVC" (streamtype 0x24) now is shown instead of "unknown".**

3.3 Backend

- **IP-out:
Limit of IP out services is now correct shown as 78 instead of 96.**
- **NIT:
Changed the default network ID.**

4 Bug fixes

List of bug fixes corrected in release 5.1.1.42586, since last release 5.0.1.41682.

4.1 General:

- **Samsung DRM:
Services were not shown in Samsung CAS.**

4.2 Backend

- **CAM:
Tivusat CAM was not working correct and stopped descrambling**