

Release description TDcH SW 2.1.0

TDcH Compact Headend

Release date: 2021-09-14

New Features release 2.1.0 since last release 2.0.0:

- Integrated multi switch supports not SCR signalling
- LNB LOF-frequencies can now be adapted (changed) to the used LNB's.
- Possible to set (static) NIT and SDT version number manual.

Solved Issues and changes in release 2.1.0 since last release 2.0.0:

- During a reboot, sometimes a tuners could fail to lock again.
- PCR correction for COFDM
- CAM: PMT was not resent correctly with ER (Error Recovery)
- CAM: CA module was not reset in rare case at power on.

Known issues:

- None

Not implemented:

- Input LED and output LED are off. The status function for these LED is not implemented yet.